Application No. 10/008,838

BEST AVAILABLE COPY

## **Amendments to the Abstract:**

Please delete the Abstract of the Disclosure and insert in place thereof the following rewritten Abstract:

A method of fabricating an [[An]] acoustic resonator includes forming a ferromagnetic compensator, such as one comprised of a nickel-iron alloy, which at least partially offsets temperature-induced effects introduced by an electrode-piezoelectric stack. The compensator has a positive temperature coefficient of frequency, while the stack has a negative temperature coefficient of frequency. By properly selecting the thickness of the compensator, temperature-induced effects on resonance may be neutralized. Alternatively, the thickness can be selected to provide a target positive or negative composite temperature coefficient of frequency. In the preferred-embodiment, the compensator is formed of a nickel-iron alloy, with the most preferred embodiment being one in which the alloy is approximately 35% nickel and approximately 65% iron. In order to prevent undue electromagnetic losses in the ferromagnetic compensator, a metallic flashing layer may be added to at least partially enclose the compensator.

## This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
COLOR OR BLACK AND WHITE PHOTOGRAPHS
GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
D

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.